Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Removal of Debries and desilting of drain inward No.17 J P Park in Yeshwanthapura sub division.
2	Administration Approval & Date	EE/RRND/AS/44/2017-18 Dtd.03-7-2017 by EE RRND
3	Technical Sanction Estimate No.& Date	EE/RRND/TS/13/2017-18 Dtd.03-07-2017 by EE RRND
4	Estimate Amount	Rs.10.00 lakhs
5	Job Code No.	017-17-000002
6	P-Code	P-1771
7	Agreement No & date	EE/RRND/AG No./188/2017-18 Dtd.15-03-2018
8	Work order Number & Date	EE/RRND/Wo No./0111/2017-18 Dtd.15-03-2018
9	Contract Amount as per Agreement	Rs.9,99,969/-
10	Bill Amount	Rs.9,99,970/- 1st & Final bill
11	S.B.R. No. & Date	06/2018-19 Dtd:19-5-2018
12	Agency	Pradeepa K.A
13	M.B. Number & Page No. of Measurement recordes	1680/17-18 Pages.167909 to 167910/1
14	Date of Inspection	20-6-2018
15	Enclosures	1) 04.Number of photos taken during inspection
16	Inspection Report	The above site Location has been Inspected by me along with the Concerned Engineer. It is observed that the Items indicated in the MB are not susceptible for measurements, as such the photos taken during the execution of work had been scrutinised and Inspected. It appears that the above work had been done. This has a reference to the EE(RRN) letter No EE/RRN/PR/73/18-19 Dated 20-6-2018

EE R.R.Nagara Division

20/6/2018
(R.Sathyanarayana)
Inspection Report officer,

R. SATHYANARAYANA
INSPECTION OFFICER

Scanned by CamScanner